

The latest firmware has been released for Beam Iridium DriveDOCK Extreme Docking Station and has now been made available for download on our website.

**The releases include the following:**

**Supported Firmware:**

- Firmware V1.6 - DriveDOCK Extreme
  - Time module updated to handle new Iridium EPOCH rollover in Feb 2026.
- Firmware V1.3 - PotsDOCK Extreme
  - Time module updated to handle new Iridium EPOCH rollover in Feb 2026.

**Eagle Version: 2.2.3**

- **Released: 29th April, 2025**
- **Supports: Iridium Extreme Handset Firmware HL21001 and Extreme PTT Handset Firmware HP23001**
- **Supports: DriveDOCK Extreme, PotsDOCK Extreme**
- **O/S Supported: Windows 2000, XP(SP3), Vista, 7, 8, 8.1, 10, 11**
- **Installation package includes Eagle software application, USB drivers and firmware**

**Overview:**

The Eagle allows users to configure a range of software options contained within the DriveDOCK Extreme and PotsDOCK Extreme hardware.

- View the status of the unit
- Configure tracking settings
- Configure POTS settings
- Configure general settings
- Store/Edit/Retrieve docking station settings
- Resetting docking station to the factory defaults
- Modifying supervisor PIN of the unit
- Beam Dock Firmware Upgrade

**Revision History:**

*Version 2.1*

- Support for PTT handset in Iridium voice mode.

*Version 2.0*

- Support for Push-to-Talk with DriveDOCK Extreme.
- Supports: Iridium Extreme Handset Firmware HL19004 and Extreme PTT Handset Firmware HP19004

*Version 1.5*

- Provides support for Wireless and Corded PTT handset in Phone mode.

*Version 1.4*

- Support for Push-To-Talk for the DriveDOCK Extreme

*Version 1.3*

- Improvement - Time module updated to handle new Iridium EPOCH
- Improvement - USB driver support for Windows 8

*Version 1.2*

- Enhancement - Supports both DriveDOCK and PotsDOCK Extreme
- Enhancement - Includes latest firmware
- Enhancement - DriveDOCK Extreme firmware version 1.2.7594

- Enhancement - PotsDOCK Extreme firmware version 1.1.7594
- Improvement - Improved tracking module
- Improvement - Improved call handling

*Version 1.0*

- Initial release of Eagle
- Firmware included - Version 1.0.6629

**Installation Notes:**

Eagle requires Microsoft .Net Framework 3.5, if your PC does not have this installed please visit <https://www.microsoft.com/en-au/download/details.aspx?id=21> and follow instructions to download and install.