

Latest firmware release for the Hands Free Interface unit (for SatDOCK 9555): Version 2.4

The following tool may be used to upgrade the firmware operating within the Hands Free Interface unit. It is recommended to only upgrade the firmware if you have been recommended to do so by a Beam support representative.

To upgrade the firmware of the HFI will require a special programming cable, CBLASY003201, which can be purchased from Beam Communications or the end user can build their own. Information on how to make this cable is included as a PDF in the download.