

The latest Falcon version 2.3 has been released for Beam Inmarsat Terminals and Docking Stations and has now been made available for download on our website.

**The releases include the following:**

- Windows 10 support for Inmarsat transceiver firmware upgrade version 5.17.2 (Oceana 800/400 and Terra 800/400)

**Supported Firmware:**

- Terminal Firmware V1.4 - Oceana 800/400 & Terra 800/400
  - Inmarsat Transceiver Firmware V5.17.2
- Terminal Firmware V1.5 – IsatDock MARINE, IsatDock PRO, IsatDock DRIVE, IsatDock LITE
- Terminal Firmware V2.0 – IsatDock2 MARINE, IsatDock2 PRO, IsatDock2 DRIVE, IsatDock2 LITE

**Falcon Version: 2.3**

- **Released: 13th September 2017**
- **Supports: Oceana 800, Terra 800, Oceana 400 & Terra 400, IsatDock MARINE/PRO/DRIVE/LITE**
- **O/S Supported: Windows 2000, XP(SP3), Vista, 7, 8, 10 (Transceiver Firmware upgrade only)**
- **Installation package includes Falcon software application, USB drivers and firmware**

**Overview:**

The Falcon allows users to configure a range of software options contained within the IsatDock and Oceana and Terra hardware.

- View the status of the unit
- Configure tracking settings
- Configure POTS settings
- Store/Edit/Retrieve docking station settings
- Resetting docking station to the factory defaults
- Modifying supervisor PIN of the unit
- Beam Terminal Firmware Upgrade

**Revision History:**

*Version 2.2*

- Support Inmarsat transceiver module 5.17.2

*Version 2.1*

- Support Inmarsat transceiver module 5.11.0

*Version 2.0*

- Enhancement - Support for signed USB drivers
- Enhancement - Support for Windows 8
- Enhancement - Support Inmarsat core module 5.6.1 for the Oceana and Terra terminals

*Version 1.9*

- Improvement - Latest firmware Oceana 400
- Improvement - Supports tracking for Oceana 400
- Enhancement - Supports Inmarsat core module 5.5.1 Version 1.8

*Version 1.8*

- Improvement - Includes Oceana/Terra 800 firmware 1.3
- Improvement - Includes Oceana/Terra 400 firmware 1.3
- Improvement - Includes IsatDock firmware 1.5
- Enhancement - GPS location is now available in status
- Enhancement - Caller ID support

- Enhancement - Supports Inmarsat core module 5.3.0

#### *Version 1.5*

- Improvement - Includes Oceana/Terra 800 firmware 1.1
- Improvement - Includes Oceana/Terra 400 firmware 1.1
- Improvement - Includes IsatDock firmware 1.3
- Enhancement - Inmarsat Transceiver upgrade support for Windows Vista/7 64-bit OS
- Enhancement - Supports sending long/multi segment SMS
- Enhancement - Supports multiple language SMS
- Improvement - Improved SMS module
- Improvement - Improved tracking module
- Improvement - Improved audio module

#### *Version 1.4*

- Enhancement - Includes Oceana/Terra 800 firmware 1.0
- Enhancement - Includes IsatDock firmware 1.2

#### *Version 1.3*

- Enhancement - Supports Oceana 400
- Enhancement - Supports Terra 400
- Enhancement - Includes Oceana/Terra 400 firmware 1.0

#### *Version 1.2*

- Enhancement - Includes IsatDock firmware version 1.2
- Improvement - Improved tracking module
- Improvement - Improved Beam Terminal upgrade module

#### *Version 1.1*

- Enhancement - Reports to user when an IsatPhone is operating less than the recommended 4.0 firmware release
- Improvement - Minor updates and fixes

#### *Version 1.0*

- Firmware Included - Version 1.1
- Enhancement - Data support
- Improvement - Tracking and integration with LeoTRAK-Online (DRIVE and MARINE models)
- Improvement - Improved management of the IsatPhone
- Improvement - Range of minor fixes and enhancements

#### **Installation Notes:**

Falcon requires Microsoft .Net Framework 3.5, if your PC does not have this installed installation process will download the necessary files needed during installation (Internet access required).